USDA-FOREST SERVICE 6P0 94 Index J-21 " File No.	CORNER RECORD (SEARCH), Tract or (Ref. FSM 7151.4) Survey No	Cor. Sec 6
т <u> </u>	R.D. Wolf. County Umotillo	
Merid. <u>Willamette</u>	N.F. Umatilla State Oregon	
11 12 12 13	Stone that appears to be corner, scribed on 4(2) on the south and what appears as - 1 on	the stone the East.
PHOTO IDENTIFICATION DATA Photo No. Filed At.	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUN 4 BT's found 2 BT's are white fir, have BT signs and viscribing, however, the bearings vistheesis reversed. 2 Douglas Firs with scribing grown over.	isihle
Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO	O HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA	1	
StateZoneX YEstab. By		
CECENOS THEER R	Forester Division Headquarters Date W.W. 9/7	* /100=9/ 13/68)/X/

CORNER	RECORD (PERPETUATION)
WORK DONE	TO DESCRIVE EVICTING MONIMENT

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Painted all BT's with red paint.

		_10
Work Done By Title Dote	State Registration No or Agency	
Certified Cor. Record Prepared ? Yes No Filed At:	Date	11
REMARKS		

Cor,