USDA-FOREST SERVICE	
Index F. 76-03.0	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No. 061411 No. 2
T 4N R 38E	R.D. <u>Walla Wall</u> a County Umatilla
Merid. Willamette	N.F. Umatilla State Oregon
CORNER DIAGRAM TRO61411 COR 2 N 2001 PLS 1106	DESCRIBE CORNER MONUMENT FOUND None. This corner was established and monumented as part of this survey. DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND None.
PHOTO IDENTIFICATION DATA Photo No Filed At Object Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone X	Corner is located on flat ground, near cabins, East of the North-South centerline of Section 7 and about 100' North of the Walla Walla River.
Estab. By Agency 8 Signature Will. R. W	Allo PLS Pendleton, OR 9-26-01 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT
At position determined by survey, set a 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap, 24" in the ground surrounded by a mound of earth and stone. Set steel fence post Southwest of corner and attached signs 54-2 and 54-4 to post. Cap is marked as shown in diagram.

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 20" ponderosa pine bears N41 1/2°E, 18.4', scribed COR 2 TR061411 BT-BT

on double blaze. An 11" Douglas fir bears S67 1/2°E, 21.8', scribed

COR 2, TR061411 BT-BT on double blaze. Painted face of blazes only,

did not attach signs to bearing trees. Nailed brass washer stamped

"PLS 1106" on bottom of blaze of each bearing tree.

· · · · · · · · · · · · · · · · · · ·	***		10
Work Done By. W.R. Wells Title	PLS	Date 08/61 State Registration No.	PLS 1106
Certified Cor. Record Prepared ? Yes X No	Filed At: Um.		09/01
	REMARKS		

Witnessed by:
Jason Wells, LSIT
Mark Hammersla

Index File No.

Cor. 13

061411

38E Willamette Tract or Surv. No.

2