USDA-FOREST SERVICE	
Index File No. <u>F.80-03</u> T <u>4N</u> R. 38E	CORNER RECORD (SEARCH)  R.D. Walla Walla County Troct or Survey No. 061411 No. 3  Umatilla
	N.F. Umatilla Stote Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
TR061411 COR 3	None. This corner was established and monumented as part of this survey.
2001	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PLS 1106	None.
PHOTO IDENTIFICATION DATA  Photo No. Filed At. Object_Ident. Ident. By  Signature 7  PLANE COORDINATE POSITION DATA  State Zone X Y Estab. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER—Witness corner is located on flat ground, on the North-South centerline of Section 7, about 40 feet North of the Walla Walla River Trail and 75 feet  North of the Walla Walla River.
Willin R. Wes	PLS Pendleton, OR 9-26-01 5

## CORNER RECORD (PERPETUATION)

MONUMENT DESCRIBE NEW MONUMENT SET OR WORK DONE TO PRESERVE EXISTING MONUMENT Corner falls in 30" dia. White fir (in poor condition), therefore set a witness corner S 01°00'21" W, 3.00' from corner point, a 2 1/2" x 30" aluminum pipe with a 2 1/2" aluminum cap 24" in the ground, surrounded with a mound of earth and stone. Set steel fence post South of corner and attached signs 54-2 and 54-4.

ACCESSORIES : DESCRIBE NEW 81's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE A 21" ponderosa pine bears S72 1/2°E, 40.1', scribed "X" at breast height and "BT" at base. A 6" white fir bears S13 1/2°W, 17.7', scribed "X" at breast height and "BT" at base. Bearing trees have a brass washer stamped "PLS 1106" nailed to face of blaze, painted blaze faces only, on bearing trees. Did not place signs on bearing trees.

			10
Work Done By W.R. Wells Title	PLS Date	State Registration No.	PLS 1106
Certified Cor. Record Prepared ? Yes X No	Filed At: Um. Co.	Sur. Off. Date	09/01
***	REMARKS		

Witnessed by: Jason Wells, LSIT Mark Hammersla

т.

Index File No.

Cor.

38E

R.

4 N

Tract or Surv. No. Willamette

061411