History of original corner establishment:

A. Corner not established by GLO

TAN R38F WM
CN1/16
1 1989

Description of corner evidence found:

B. MONUMENT FOUND:

none

Description of monument and accessories I established to perpetuate the original location of this corner:

C. I set in place a 2.5 inch dia. by 30 inch long aluminum monument 25 inches in the ground. No stones available.

T mark the cap:

TAN P38E WM
N 1/16
C
S29 + C
1989
STRYKER PLS 2060

NEW ACCESSORIES ESTABLISHED with magnetic declination of 21 deg. East

25" spruce bears N80F at 25.4 ft scribed "CN 1/16 S29 BT" 10" spruce bears S46W at 52.3 ft scribed "CN 1/16 S29 BT"

Painted red band around each bearing tree.
Placed brass washer marked "PLS 2060" at base of blaze on each new RT
Placed USDA Forest Service metal signs 54-3 (BT) and 54-4 (ATTENTION)
on each bearing tree.
Placed 54-9 (LSM) and 54-2 (PROPERTY BOUNDARY) on steel fence post set
5 feet south of corner.

Office of Survey Dept coun	ma Umatilla
State of	within instrument was filed in this office
for pecord on the Com day of NOUS MAN	2.19.7 J 1
(COUNTY OFFICIAL)	(DEPUTY) REGISTERED

Form R6-7100-57 (9/71)

RECEIVED BY

Umstilla County Surveyor

No. 89-107-B

PROFESSIONAL LAND SURVEYOR

OREGÓN JULY 15, 1983 EDWIN A. STRYKER 2060