USDA-FOREST SERVICE				· · · · · · · · · · · · · · · · · · ·
Index File No. <u>T-1戈</u>	CORNER REC (Ref. )	ORD (SEARCH) FSM 7151.4)	Tract or Survey No	Cor. No
T <u>4N</u> R. <u>38E</u>	_R.D. <u>Walla Walla</u>	County Um	atilla	
Merid. Willamette	N.F. <u>Umatilla</u>	State Or	egon	
CORNER DIAGRAM	DESCRIBE CORNER MON	UMENT FOUND		
T4N R38E W 1/16	with the grou	nd.	∠ž" galv. ir	on pipe, flush
C C	-		t.	·.
1980 RLS 934	I DIAZE (UTO A	<i>241</i> Own englemar	in spriide hoe	with healed doubl
PHOTO IDENTIFICATION DATA	with beilbeb	visible on (	iouble blaze.	(RLS 934)
Photo No	_	•		
Object Identident. By	_  Corner is Loca	ated near th	ne west side	50 HOW TO REACH CORNER of a clearcut,
PLANE COORDINATE POSITION DATA	direction.	st of a roac	running in	a southwesterly
State Zone	-		-	
XY	<u>-</u>			•
Estab. By	8			
Will R. Wells		ision Headqu		10-1100-02 (0100)
	PLS	Pendle	ton, OR 9/4/	<sup>1</sup> 91

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Maintained monument by cleaning up around it and mounding with earth. Set steel fence post south of corner with signs 54-2 and 54-9 attached.

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Marked 1 new bearing tree:

A 19" western larch bears S  $28\frac{1}{2}$ °W, 24.1' scribed C-W 1/16 S27 BT.

New bearing tree has a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around all bearing trees.

		10
Work Done By W.R. Wells Title_	PLS Date 9/4/91 State Registration No. 1106	
Constitution of the second second		
Certified Cor. Record Prepared 7 Yes X No	Filed At: Umatilla Co. Surveyor Off Date /2/9/	••
	REMARKS	

Index File No. T. R. M. Tract or Surv. No. Cor. 13