USDA-FOREST SERVICE INDEX FILE NOT-3 T4 NR38 E WeridWillamette	CORNER RECORD (SEARCH) Tract or Cor.  (Ref. FSM 7151.4) Survey No.
CORNER DIAGRAN TAN R38E 1 1 1 C530 N 4 1 1995	l DESCRIBE CORNER NONUMENT FOUND l Corner not previously set. l l
PLS 852  PHOTO IDENTIFICATION DATA Photo No. Filed At. Object Ident. Ident. By Signature	_l
XYEstab. By	
_	e Division Headquarters Date FS-7100-52 (3/68) Veyor Pendleton, OR 9-04-95

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMEN Set a 2 1/2" X 30" alum the corner diagram on t	ninum pipe and cap 26" int he opposite side of this	its the ground with a 20% mound of others are all 11
A 9" dbh Douglas Fir bear A 9" dbh White Fir bear A 14" dbh White Fir bear A 8" dbh Alpine Fir bear A brass washer stamped ORLS 852 a	ars N70°24'W, 21.6' scribe s N79°35'E, 41.7' scribed rs S51°33'E, 85.0' scribed rs S13°18'E, 20.0' scribed and WALS 13922 is nailed b	d C 1/4 S30 BT,
Work Done ByDavid L. Haddock_ Certified Cor. Record Prepared?	Title_Land Surveyor x Yes	State Registration NoDate_8-16-95or AgencyPLS 852 No Filed At: Umatilla County Surveyor Date9-95
	RENA	
• • • • • • • • • • • • • • • • • • •		

Cor.