? of ?

History of original corner establishment:

N. Corner established by US Deputy Surveyor Frank W. Campbell under his contract number 46% dated April 12, 1883. (history continued next page)

Surveyor General's Pecord states:
Set a post 3 1/2 ft long 3 ins square
with marked stone 24 ins in ground for 1/4 sec cor
marked 1/4 S on W face from which
A fir 13 ins dia bears N53W 7 1ks dist marked 1/4S BT
A fir 12 ins dia bears S23F 33 1ks dist marked 1/4S BT

TAN P38F WM 1/4 230 + 229 1939

Description of corner evidence found:

B. MONUMENT FOUND:

found a 2.5 inch dia brass cap on 1 inch iron pipe 7 inches exposed; no stones. The cap is marked:

U.S. General Land Office Survey Penalty \$250 For Removal

930+929

ACCESSORIES FOUND:

1939

23.5" dia spruce bears N50W at 8.0 ft with healed blaze--did not open Umatilla County Surveyor BT metal sign "9/24/72 AJL" on 23.5" spruce 31.0" dia spruce bears S41E at 3.3 ft with healed blaze--did not open

Description of monument and accessories I established to perpetuate the original location of this corner:

C. cleared area around the monument

NEW ACCESSORIES ESTABLISHED with magnetic declination of 21 deg. East none-both spruce bearing trees in stable healthy condition

Painted red band around each bearing tree.

Placed MSDA Forest Service metal signs 54-3 (8T) and 54-9 (LSM) on each bearing tree.
Placed 54-9 (LSM) sign on steel fence post set 1.4 ft north of corner Placed 54-4 (ATTENTION) sign on tree near corner

Office of Suns y Ost County of Umatella

State of hereby certify that the within instrument was filed in this office for second on the Co. day of NOTEMBER. 1989

David H. Launden by Kallein & Ambrus

Form R6-7100-57 (9/71)

RECEIVED BY

Umanule County Surveyor

100 89-107-B

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 15, 1983 EDWIN A. STRYKER

History of original corner establishment:

A. (cont). Corner remonumented by U.S. Deouty Surveyor Otis O. Gould under special instructions dated July 11, 1939, which provided for the surveys included under Group No. 234, bearing the approval of the Commissioner of the General Land Office under date of July 27, 1939.

DIAGRAM

TAN R38E WM
1/4
530 + 529
1939

The Surveyor General's Record states:

Proportionate measurement.

Description of corner evidence found:

Set an iron post; 3 ft. long, 1 in. diam., 27 ins. in the ground, for 1/4 sec. cor., with brass cap marked

1/4 530+529

1939

from which

A spruce, 34 ins. diam., bears S.41F., 5 lks. dist., marked 1/4 S 29 B T.
A spruce, 26 ins. diam., bears N.50W., 12 lks. dist., marked 1/4 S 30 B T.

Description of monument and accessories I established to perpetuate the original location of this corner:

Office of Survive Dept ... County of Unatilea

State of ... OR ... I hereby certify that the within instrument was filed in this office for record on the ... day of ... Da is more by ... 1989

COUNTY OFFICIAL)

REGISTERED

Form R6-7100-57 (9/71)

RECEIVED BY

Umattha December Surveyor

Dato 11-87

OREGON JULY 15, 1983 EDWIN A. STRYKER

2060

PROFESSIONAL

LAND SURVEYOR