| USDA-FOREST SERVICE | • |
|--------------------------------|---|
| Index T-9 | CORNER RECORD (SEARCH) Tract or Cor. |
| T 4N R. 38 E | |
| Merid | N.F. UMATILLA State OREGON |
| CORNER DIAGRAM | DESCRIBE CORNER MONUMENT FOUND |
| 1/4 | 2/2" Brass CAP ON I" FrON PIPE |
| 1 / 7 | 911 exposed w/o stones; |
| 29.28 | all exposed w/o stones; CAP Marked: us General Land Office Survey Penalty #250 For Removal. |
| 7 619 60 | DESCRIBE BEARING TREES OR OTHER OFFICIAL AGGESTINES TOURD |
| | 1 |
| 1 | 14" LP.P.ne bears 562 F 1989 |
| | at 7,3 ft scribed "Y45 28 BT" |
| PHOTO IDENTIFICATION DATA | Western harch Stump with healed blaze at buse |
| Photo No. | hadre with the second |
| Filed At. | bears NB4W at 5.39 ft. |
| Object Ident. | DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER |
| Ident. By Stanature | DRIVE ON 6401 RD TO TOP RIDGE AND |
| PLANE COORDINATE POSITION DATA | |
| = | TO LEFT Approx 600 Ft SOUTH OF JNCTN. |
| State Zone | WITH SPUR 040, CORNER LOC. THE ON |
| Ŷ | |
| Estab. By | EAST SIDE 6401 RD. HIKE EAST Approx. |
| Agency 8 | 300 ft to corner. |
| dum a stylen | Title Division Headquarters Date FS-7100-52 (3/68) |
| | |

RECORD (PERPETUATION)

cleaned area around monument Placed location poster on road 6401.

18" Spruce bears 527W at 22.4 ft scribed " 14529 BT" Placed brass-washer PhS 2060 at base of blaze

| , | 01.1. | | | | | |
|---------------------------|-----------------|----------------|-------------|-----|---------------|-------|
| Work Done By FA | | | | | 110n No. 2060 | |
| Certified Cor. Record Pre | pared? (Yes) No | Filed At: (/MA | TILLA | CTY | Date AUG | 89 |
| Painted al | / RT-1c. | WITH RED | | | | 7 × 1 |

Placed 54-4 sign near corner placed 54-9 sign on steel fence post set

| USDA-FOREST SERVICE GF | 940-117 |
|------------------------------|--|
| Index File No. <u>T-9</u> | CORNER RECORD (SEARCH) Tract or Cor. T-9 (Ref. FSM 7151.4) Survey No No No |
| T <u>4 N</u> R. <u>38</u> | R.D. Walla Walla County |
| Merid. <u>Willamette</u> | N.F. Umatilla State Oregon |
| CORNER DIAGRAM | DESCRIBE CORNER MONUMENT FOUND |
| Section 29 | Brass Cap. Size: 2½". |
| T I T | DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND |
| | All bearing trees as described in notes. |
| PHOTO IDENTIFICATION DATA | 6 |
| • | |
| Photo No Filed At. | |
| Object Ident. | DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER |
| ldent. By | DESCRIBE COMMEN ECCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER |
| Signature | 7 |
| PLANE COORDINATE POSITION D | TA |
| State Zone | |
| x | |
| Υ | |
| Estab. By | |
| Signature | Title Division Headquarters Date 7100-52 (3/68) |
| B, Moore | Title Division Headquarters Date 7100-52 (3/68) Ingineering Technician S. O. July 1975 |
| -1 -0-1 | <u> </u> |

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Paced 210' north to power line clearing and put up Forest Service location poster.

Also placed Forest Service B.T. posters on the bearing trees (4).

| <u> </u> | | | 10 |
|---|-----------|---------------------------------|--------|
| Work Done ByTitle | Date | State Registration No or Agency | |
| Certified Cor. Record Prepared ? Yes No | Filed At: | Date | 11 |
| | REMARKS | | |

Index File No.

- 开。

R,

M.

Tract or Surv. No.

Cor,

13