
History of original corner establishment:

James D. Hanley originally established this corner in July 1976 under contract # 004971N Set a 2"x 30" iron pipe with a brass cap stamped as diagram 24" in ground and placed a mound of stone to top.

from which a 13" fir bears S 23° W 16.5 ft.
no other BT's



Description of corner evidence found:

Found 2" iron pipe in mound of stone with B.C. stamped as diagram. from which a 13" fir bears S 23° W 16.5 ft. 1/16 S 34 BT visible. a steel fence post is driven 3 ft east of corner

Description of monument and accessories I established to perpetuate the original location of this corner:

New bearing tree; A 15" fir bears N 13° E 18.4 ft. scribed E 1/16 S 27 BT Note; the trunk of the above tree is bowed. the bearing and distance is taken to the center of the tree at the center of the blaze.

I nailed an alum. tag # 951 to the bottom of the blaze and painter both blazes red. Painted red bands around BT's and attached 54-3 and 54-9 signs.

Attached a 54-9 sign to fence post.

I hereby certify the above corner location was perpetuated as herein described in July ,1985

REGISTERED PROFESSIONAL LAND SURVEYOR

S. Donnie Eliverd

OREGON
JULY 18, 1971
G. DENNIS EDWARDS

951

ful Gament Jud Coppock

Office of	County of
	that the within instrument was filed in this office
for record on the day of	
	by
(COUNTY OFFICIAL)	(DEPUTY)
for record on the day of	

RECEIVED BY

Form R6-7100-57 (9/71)

Umatilla County Surveyor

Date 8-6-85
Rec'd By XA

No. 85-104-R

☆ GPO—798-276