History of original corner establishment: None

DIAGRAM	
W 1/1	6
C	- C
S 34	

CW 1/16 S 34

LS 951

Description of corner evidence found:

Found 2" iron pipe N 340 00' 31" W 22.00 feet from corner.
no record

Description of monument and accessories I established to perpetuate the original location of this corner:
Set a 2" x 30" iron pipe 29" in ground with brass cap stamped from which:
a 16" fir bears N 60° E 9.5 feet scribed CW 1/16 S 34 BT a 10" fir bears S 15° E 11.4 ft. scribed CW 1/16 S 34 BT

I nailed alum. tags stamped 951 to bottom blazes and painted blazes red. Painted red band around BT's and nailed USFS signs 54-3 and 54-9 to them.

Drove a steel fence post 3 ft east and attached 54-9 sign.

I hereby certify the above corner location was perpetuated as herein described in July 1985.

Jul Coppock , Witness

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 18, 1971
G. DENNIS EDWARDS

Office of	County of	
	I hereby certify that the within instrument was filed in this office	
	, 19	
(COUNTY OFFICIAL	RECEIVED BY (DEPUTY)	20
Form R6-7100-57 (9/71)	Umatilla County Surveyor	фаро-
	Date_8-6-85	
	Boold Day of A	