## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

X-17 T 4 N R 38 E

History of original corner establishment: Corner originally established by Frank W. Campbell under contract # 468 dated April 12, 1883. Set a basalt stone 12"x10"x6", 8"in ground marked t on West face . from which:

DIAGRAM S 34 | S 35 1939

In a U.S. Dependent resurvey by Otis O. Gould in August 1939 the stone was found and a 1"x36" iron pipe with a brass cap marked as diagram was set 27" in ground with a mound of stone.

Old BT A 32" fir bears S 65° E 12 lks(7.9 ft.)
Old BT A 30" fir bears S 87½°W 85 lks (56.1 ft.)

Description of corner evidence found:

Found 1" iron pipe with brass cap marked as diagram in a mound of stone.

from which:
A 36" fir bears S 65° E 7.9 ft. some marks vis. on choped out blaze.
A 33" fir bears S 87½° W 56.1 ft Blaze Healed not opened.

Description of monument and accessories I established to perpetuate the original location of this corner:

I drove a steel fence post 3 ft. N.E. of corner and attached a 54.4 sign.

A 7" fir bears N 56° W 37.1 feet scribed 1/4 S 34 BT

I nailed an alum. tag to bottom blaze of new tree and painted all blazes red. Painted a red band around all BT's and attached 54-3 and 54-4 signs to them.

I hereby certify the above corner location was perpetuated as herein described in July, 1985

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

Office of	County of
	that the within instrument was filed in this office
for record on the day of	
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

Date 3-6-

₩ GPO-798-276