## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

Corner established by George S. Pershin under GLO Contract No. 304 dated Sept 19, 1978 Iron Post with Brass Cap established by Otis S. Gould, BLM Surveyor in July 1939 during Dependent Resurvey of part of Subdivision of T4N, R38E from which:

2-5 DIAGRAM R 38 E 31 32 6 T3N

A Pine 14" dia. S  $45^{0}$ W 12 1ks mkd R 38E BT (old BT) A dead Tamarack 16" dia, N  $70^{0}$ W 18 1ks mkd T4N, R38E S31 BT (old BT)


A Spruce 20" dia. N 4½°E 18 1ks mkd T4N, R38E S 32 BT (New) A Spruce 18" dia. N 49°W 37 1ks mkd T4N, R 38E, S 31 BT (New)

## Description of corner evidence found:

Iron Post 2" dia, set 24" in ground with Brass Cap marked:

Found

12" Spruce bears N  $22^{0}$ W 15.50 ft. mkd T4N, R 38E, S 31 BT



Description of monument and accessories I established to perpetuate the original location of this corner

Scribed:

A 13" Douglas Fir N  $32^{\circ}$ E 36.1 ft mkd T4N, R38E, S 32 BT A 10" Douglas Fir S  $27^{\circ}$ E 18.5 ft mkd T3N, R38E, S 6 BT

Blazes are painted red, trees have red bands painted around them and have signs number 54-3, 54-4, and have Brass Washers stamped PLS 933 nailed to them.

November 1982

By: D. Krumbein Witness: R.D. Punches

B.J. Reynolds

PROFESSIONAL LAND SURVEYOR

OREGON DAVID H. KRUMBEIN 933

Office of Surveyor	County of Umatilla
State of Oregon , I hereby	certify that the within instrument was filed in this office y 1983
for record on the 22 day of	y 1983
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY

Umatilla County Surveyor

Date 9-13-83

Rec'd by B CGPO 796-199

No. 83-172-P