CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Index: Z-5

Cor. Secs. 31 and 32, T.4N., R.38E., W.M.
Original corner was set by Pershin in June 1879.
His notes record:
Set Fir post for cor. to Sec. 31, 32, 5 and 6:
A Tamarack 8 ins. di. brs. N.42°E. 16 lks. dist
A Pine 10 ins. di. brs. S.80°E. 18 lks. dist
A Pine 10 ins. di. brs. S.56°W. 12 lks. dist
A Tamarack 10 ins. di. brs. N.70°W. 18 lks. dist
In 1939, the GLO remonumented this corner.
Their record reads:

1 DIAGRAM 1
1 1
1 T4N R38E 1
1 S31 1 S32 1
1 ---- 1
1 T3N R38E 1
1 S6 1
1 1939 1
1 1

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap marked (diagram) from which

A pine, 14 ins. diam., brs. S.45°W., 12 lks. dist., marked R38E BT. A dead Tamarack, 16 ins. diam., brs. N.70°W., 18 lks. dist., marked T4N R38E S32 BT. A spruce, 20 ins. diam., brs. N.4 1/2°E., 18 lks. dist., marked T4N R38E S32 BT. A spruce, 18 ins. diam., brs. N.49°W., 37 lks. dist., marked T4N R38E S31 BT.

In 1982, PLS 933 added 2 new BT's to this corner. They are described: A 13" Douglas Fir N32°E 36.1 ft mkd T4N, R38E, S32 BT. A 10" Douglas Fir S27°E 18.5 ft mkd T3N, R38E, S6 BT

Description of corner evidence found:

Found the iron pipe as described with brass cap stamped as shown in the diagram. From this monument:

A 14" dbh White Fir, dead and down, N26°52'W, 15.5' with visible BT scribe. A 21" dbh Engleman Spruce N35°57"E, 36.6' with partially healed scribed blaze A 15" dbh White Fir S27°30'E, 18.7' with partially healed scribed blaze.

Description of monument and accessories I established to perpetuate the original location of this corner:

The bearings were based on the surveyed bearing between this section corner and the 1/4 corner to the east as recorded by RPE 2808 in a filed Umatilla County survey. I set the following new witness trees:

A 20" dbh Engleman Spruce bears N22'30'W, 22.8' scribed T4N R38E S31 BT;

A 18" dbh Engleman Spruce bears S18'17'W, 18.0' scribed T4N R38E S5 BT.

An aluminum washer stamped RLS 852 is nailed between the letters B and T on each new tree. All four living trees have LSM and BT signs attached. Painted 6" red bands around all four living trees and painted the scribe blazes red.

This work was done July 11, 1992.

PROFESSIONAL LAND SURVEYOR

David L. Haddock

OREGON JULY 12, 1958 DAVID L. HADDOCK 852

Office of	County of				
State of in this office	for record on	certify the	that the withi	n instrument	
(COUNTY OFFICIAL)			(DEPU	TY)	

Form R6-7100-57 (9/71)

RECEIVED BY
Umatilla County Surveyor
Date 8-92
Rec'd By