CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

90	\$34
None.	T3S_R31 <u>E</u>
No record of corner establishment appears in County Records	
	T4S R31E
Description of corner evidence found:	
NI WES	
None.	
Description of monument and accessories I established to perpetuate th	e
original location of this corner: I set 2 1/2" brass cap on 2 1/2" x 30" I, pipe 12" in ground	I with many of stone from which.
I set 2 1/2" brass cap on 2 1/2" x 30" 1, pipe 12" in ground	with mound of stone from which:
A 16" dia Ponderosa Pine bears S43°W 33.7 ft dist marked:	
A 19" dia Ponderosa Pine bears S43°E 79.5 ft dist marked:	E 1/16 S2 B1.
Blaze faces and 6" band around bearing trees are painted re-	
New BTs have lower blaze, scribed BT, with a brass washer Set Steel fence post with 54-2 & 9 sign attached, West of co	
Used steel tape and magnetic compass 19 3/4° East declinat	
C	
Corner monumented on October 20, 1982. Cap in	marked:
Witnessed by: Leslie E. Wilson	534
Scanning was defined a Princip Control of the State of th	
PROFESSIONAL	E 1/16 S2 T4S R31E
LAND SURVEYOR	1982
Willia R. Wells	PLS 1106
OREGON	
JULY 22, 1977 WILLIAM R. WELLS	
1106	
Office of County Surveyor County of Umat	tilla
State of Oregon I hereby certify that the within instrume	ent was filed in this office
for record on the 15 day of De comber 19.82	- 1000 KI
(COUNTY OFFICIAL)	EPUTY)
Form R6-7100-57 (9/71)	RECEIVED BY
1 olm 10-1100-01 (3/11)	Umatilla County Surveyor,
	Date
	Rec'd -y
	No. 82-138-B