USDA-FOREST SERVICE	
Index File No. <u>A - 5</u>	CORNER RECORD (SEARCH) Tract or Survey No No No
	R.D. Oktan County
Merid. Willamette	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
	MATERIAL SIZE
	HEIGHT ABOVE GROUND: CONDITION  MARKINGS Mound of basalt stump 3'x3'x8"
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	23" dia. P.Pine - S42°W - approx. 127 links from stone mound.
	Tree stated on NE face. scribed: S6
PHOTO IDENTIFICATION DATA	There is rotten pine stump in SE quadrant. (Possible BT)
	dadrant: (10881016 B1)
Photo No	
Object Ident,	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By	I Placed a Bit Tay on the 23" Pine.
Signature. 7	I Placed 4 1511, Jay on the 23" Pine,
PLANE COORDINATE POSITION DATA	
State Zone	
x	
Y	
Estab. By	
Signature Alloure	Title Division Headquarters Date 7100-52 (3/68) 9/76

	CORNER RECO			GF-0 202 07
MONUMENT: DESCRIBE NEW MONUMENT	SET, OR WORK DONE TO PRE	SERVE EXISTING	MONUMENT	
ACCESSORIES : DESCRIBE NEW BT'S WIT	NESS OBJECTS ETC. ESTABL	ISHED, OR WORK	DONE TO PRESERVE EXISTING E	VIDENCE
				;
		÷		
Work Done By	fitle	Date	State Registration No or Agency	
Certified Cor. Record Prepared ? Yes	No Filed At:		Date	
	REMARKS			
		•		
	,			
• •				

**M**. -

Tract or Surv. No.

Cor.

13

Index File No.

T.

R.