USDA-FOREST SERVICE	
Index File No. E-11	CORNER RECORD (SEARCH) Tract or Cor. (Ref. FSM 7151.4) Survey No No
T <u>4 S</u> R. <u>31 E.</u>	R.D. <u>Ukiah</u> County <u>Umatilla</u>
Merid. Willamette	N.F. Umatilla State Oregon
Sec.	DESCRIBE CORNER MONUMENT FOUND Material: Stone Mound. Markings: None visible. Steel post with paddle with 4 marked on it sets in center of mound. 2 feet South of East-West fence. Monumented By BLM, 1978 DESCRIBE BEARING TREES OR OTHER/OFFICIAL ACCESSORIES FOUND A 14" ponderosa pine bears N 40° W. 46 feet. It has State Park Location Poster on it dated 9-16-75. Tree is scribed S4, S 4, B.T. A 13" ponderosa pine bears S85° E. approximatley 75'. It is scribed N 4, S 9, B.T.
PHOTO IDENTIFICATION DATA	Stump hole of original B.T. bears N 42° E, 160 feet.
Photo No	
Filed At.	3
Object Ident.	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Ident. By Signature 7 PLANE COORDINATE POSITION DATA	½ corner location is about 2 feet South of East-West fence and about 500 feet West of Junction of Highway 395 and Albee Road.
State Zone	Noud.
x	
Υ	<u> </u> -
Estob. By	to the first of the second of
Signature W. Moore	Title Division Headquarters Date 7100-52 (3/68) Engr. Tech. 4-27-76

	CORNER	RECORD (PERPETUATION	GPO 902-
MONUMENT: DESCRIBE N	EW MONUMENT SET, OR WORK DONE		
	•	*	
ACCESSORIES : DESCRIB	E NEW BT'S WITNESS OBJECTS ETC.	ESTABLISHED, OR WORK DONE TO	PRESERVE EXISTING EVIDENCE
Work Done By	Title	State R	egistration No.
			Date
Certified Cor. Record Pre	pared? Yes No Filed At.		Dute
Certified Cor. Record Pre		MARKS	Date
Certified Cor. Record Pre		MARKS	DUIS
Certified Cor. Record Pre		MARKS	/
Certified Cor. Record Pre		MARKS	/
Certified Cor. Record Pre		MARKS	/

Tract or Surv. No.

Index File No.

T.

R.

M.

13

Cor.