Index File No. №13	CORNER RECORD (SEARCH (Ref. FSM 7151.4)	Tract or Survey No	No
T <u>4S.</u> R. <u>31E.</u>	_R.D. <u>Ukiah</u> County_		
Merid. <u>Willamette</u>	N.F. <u>Umatilla</u> State	Oregon	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND  Material: Brass Cap Size: 2½" diam.  Theight above ground: 8" Condition: Good  DESCRIBE BEARING TREES OR OTHER OF  No accessories. Corner sets		
PHOTO IDENTIFICATION DATA Photo No. Filed At.	<u>.</u>		3
Object Ident	DESCRIBE CORNER LOCATION RELATIVE 1	O NEAR-BY FEATURES, A	LSO HOW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone X Y			
Estab. By			
Signature BILL Moore	Title Eng. Tech.	odquarters D 5-25-	7100-52 (3/68)

USDA-FOREST SERVICE

GPO 902	-6	78
---------	----	----

CORNER	RECORD	(PERPET	UATION)
--------	--------	---------	---------

MONUMENT: DESCRIBE NEW MONUMENT	SEI	, OR WORK	DONE TO	PRESERVE	EXISTING	MONUMENT
---------------------------------	-----	-----------	---------	----------	----------	----------

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By.\_\_\_\_\_\_ Title\_\_\_\_\_ Date\_\_\_\_ State Registration No.

Certified Cor. Record Prepared ? Yes No Filed At: Date 11

REMARKS

\_\_\_\_