File No. J-23	CORNER RECORD (SEARCH) Tract or Cor. SEC. 1/4 COR (Ref. FSM 7151.4) Survey No. No. SEC. 12
T 4S R. 33 E WILLAMETTE	- K.D LATE ORANGE County - UNION - COUNTY
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
12	
————	
/ 3	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 1 dead larch, B.T. about 30 ft. tall marked by red ribbon and 14" in diameter. Lays N.E. of French Corral Meadow.
Photo No. EWD 17-73	
PHOTO IDENTIFICATION DATA Photo No. EWD 17-73 Filled At. O Ebject Ident. Idlent. By Signature	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
P thoto No. EWD 17-73 Filled At. O Expect Ident. Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Photo No. EWD 17-73 Filled At. O bject ident. Idlent. By Signature 7 PLANE COORDINATE POSITION DATA State Zone Y	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Photo No. EWD 17-73 Filled At. O bject ident. Idlent. By Signature 7 PLANE COORDINATE POSITION DATA StateZone	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

3. 사용하는 사용하는 보고 보고 있다는 보고 있는 그리는 그리는 그리는 전화 1. 사용하는 1
Work Done By Title Oote State Registration No.
Work Done By Title Date or Agency Certified Cor. Recard Prepared ? Yes No Filed At: Date

Index File_No. / T. R. M. Tract or Surv. No. Cor. 13