CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.

DIAGRAM			
C 4	+	535	

No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

No evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position described above, I set a $2\frac{1}{2}$ " x 30" iron pipe with a $2\frac{1}{2}$ " Brass Cap 24" in the ground with a brass cap marked as shown:

From which I scribed BT's:

A 36" Pond Pine bears S 47 $^{\rm O}45$ 'E 18.30 feet scribed C $^{\rm L}_4$ S 35 A 9" Pond Pine bears S 50 $^{\rm O}W$ 25.90 feet scribed C $^{\rm L}_4$ S 35

I nailed a brass washer marked PLS 933 to the BT blazes.

I set signs 54-3 and 54-9.


I painted a red band around the BT's and face of scribe.

I used a steel tape and a magnetic compass with $19^{0}30$ ' East variation and measured a horizontal distance to the center of BT's.

This corner was set March 1984

Witness: Rod Punches

Brent Reynolds



OREGON DAVID H, KRUMBEIN

PROFESSIONAL

Office of County Surveyor	County of Umatilla
State of Oregon , I hereby certify the for record on the low day of lower by	at the within instrument was filed in this office
for record on the	Bally Claha
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO-798-276

84-164-R