
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.



No record of subsequent remonumentation found in County Records. Description of corner evidence found: No evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the position described above, I set a $2\frac{1}{2}$ " x 30" iron pipe with a $2\frac{1}{2}$ " Brass Cap 21" in the ground, with a brass cap marked as shown:

From Which I scribed BT's:

A 7" Pond Pine bears N 64^030 'E 33.0 feet scribed CS 1/16 S 35 A 16" Pond Pine bears S 32^015 'E 105,50 feet scribed CS 1/16 S 35

I nailed a brass washer marked PLS 933 to the BT blazes.


I set signs 54-3 and 54-9.

I painted a red band around the BT's and face of scribe.

I used a steel tape and a magnetic compass with $19^{0}30^{\circ}$ East variation and measured a horizontal distance to the center of BT's.

This corner was set March 1984

Witness by: Rod Punches Brent Reynolds



PROFESSIONAL
LAND SURVEYOR

OREGON
DAVID 17, 1970
DAVID 9 33

| Office of County Surveyor | County of Umatilla |
|--|--|
| State of Oregon the State of Mereby certifor record on the State day of Mereby | fy that the within instrument was filed in this office |
| (COUNTY OFFICIAL) | by Betty Cochia |

Form R6-7100-57 (9/71)

☆ GPO-798-276

84-165-R