OREGON CORNER RESTORATION FORM

Section:

9 - 10 - 15 - 16

Township:

5 North

Range:

28 East of the Willamette Meridian

County:

Umatilla

Date:

12/23/2022

Corner Indexing Information: Township 5N Range 28E Corner Code J-13 (Willamette

Meridian)

Additional Identifier: Corner common to Sections 9, 10, 15 & 16

Oregon Plane Coordinates: N: 824814.49 E: 8505577.96 Zone: North Order: Second

Datum: NAD83-2011(epoch 2010) Convergence: N 00°50'44.60" W Scale Factor: 0.99996919936196

Previous Renewals/Surveys, etc.:

1861: Post, mound, pits, & charred stake (Davenport, General Land Office Contract #101)

1947: "No evidence found of original survey. Reported destroyed in the summer of 1946 by Mr. Davis (adjacent owner). Re-established corner by calculated tie from Corps of Engineer's location of original corner in 1944. Set hub at the edge of Ferry Road" (Kelsay, United States Army Corps of Engineers (USACE) Cadastral Record T5N-R28E Index 15)

Circa. 1950: Found United States Army Corps of Engineers (USACE) brass cap (Fraley, Q-0764-A)

Monument(s) & Accessories Found (Condition & Source):

3-1/2" brass cap found 6" deep, 14' East of old road centerline. An angle-iron post with witness post stands 1.3' Northeast; Utility pole with an aluminum tag #951 attached, bears N26°30'07"W, 84.11'.

Monument Set (Procedures & Description):

Monument Detail:

Found 3-1/2" brass cap as described in good condition.

PORTLAND DISTRICT

U.S. ENGINEER DEPARTMENT

T5N R28E 9 10 16|15

BOUNDARY MONUMENT

New Accessories: WE SET:

Set bearing object sign on a railroad tie, which bears N01°43'E, 179.49' from the corner; Set bearing object sign on a utility pole which bears N26°26'W, 84.00' from the corner; Set bearing object sign on a railroad tie, which bears S03°57'E, 20.82' from the corner; Set bearing object sign on a utility pole which bears S50°31'W, 303.62' from the corner; Set bearing object sign on a utility pole which bears N51°01'E, 400.04' from the corner.

Location & Comments:

To access monument, take US-730 to Scaplehorn Road, +/- 350' North of Brownell Ditch & Scaplehorn Road

Compass Declination:

All accessories tied with State Plane grid bearings.

Firm/Agency: PBS Engineering & Environmental, Inc.

5 N. Colville Street Walla Walla, WA 99362

Witness: Mark F. Wendover

Eduardo C. Ibarra Felipe G. Hernandez Hayden J. Lomeli

Surveyor's Seal

REGISTERED **PROFESSIONAL** LAND SURVEYOR

CRECON JUNE 30, 1997 GREG E. FLOWER FLOWERS 02820LS

RENEWS 12/31/2025 12/27/2023

J-13.DOC