

# OREGON CORNER RESTORATION FORM

SECTION 30 TOWNSHIP 5 NORTH RANGE 28 EAST

R-5

COUNTY : UMATILLA DATE 6/04

CORNER DESIGNATION

NE CORNER SECTION 30

CONDITION REPORT ONLY

NOT FOUND

RENEWED

UNCOVERED

SURVEYED IN

REFERENCED

PREVIOUS RENEWALS / SURVEYS, ETC.

ORIGINAL GLO SURVEY BY DAVENPORT UNDER CONTRACT #101 IN 1861. SET POST WITH MOUND AND CHARRED STAKE.

KRUMBEIN REESTABLISHED IT IN 1973, SURVEY # 1-16-C. SET BRASS CAP AND BRASS CAP WITNESS CORNER.

WELLS REFERENCED THE MONUMENT IN 1998, SURVEY # 98-101-C.


MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

A 2 1/2" BRASS CAP (SEE MONUMENT DETAIL)

A 3" IRON PIPE IN CONCRETE 36" ABOVE GROUND LIES N 5°00'00" E, 204.35 FEET.

A 2 1/2" BRASS CAP WITNESS CORNER LIES N 82°55'15" W, 196.15 FEET.

MONUMENT DETAIL




NAD 83/91  
OREGON STATE PLANE  
INTERNATIONAL FEET

814000.75  
8495150.91

N.T.S

SKETCH



MONUMENT SET ( PROCEDURES AND DESCRIPTION )

NEW ACCESSORIES FROM WHICH

AN ALUMINUM TAG "PLS LS 48509" ON A POWER POLE LIES N 75°35'40" E, 315.92 FEET.

AN ALUMINUM TAG "PLS LS 48509" ON A POWER POLE LIES N 88°46'50" E, 336.09 FEET.

LOCATION AND COMMENTS

FROM THE INTERSECTION OF POWERLINE ROAD WITH RADAR ROAD, GO WEST ± 1000 FEET TO CORNER ON SOUTH SIDE OF RADAR ROAD.

COMPASS DEC.

FIRM/AGENCY  
PRIMM LAND SURVEYING LLC  
P.O. BOX 1322  
HERMISTON, OREGON 97838

PARTY CHIEF  
KEITH P. PRIMM

NOTES

WITNESS  
BRIT L. PRIMM

SURVEYOR'S SEAL

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Brit L. Primm*  
OREGON  
JULY 13, 1999  
BRIT L. PRIMM  
48509

EXPIRATION DATE: 12/31/04

Aug/18/04

04-155-B