#### OREGON CORNER RESTORATION FORM T-1 RANGE: 29E TOWNSHIP: 5N SECTION:30 **DATE**: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED UNRECORDED W1/4 Section 30 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In a 1988 county monumentation survey Edwards set 1"x30" iron pipe with a 2 3/8" brass cap stamped as

# MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Found 2 3/8" brass cap stamped as below 10" below the surface of a graveled road. W.C. an aluminum tag #951 in a R/R tie fence post bears S 49° 15' 22" W 31.87'(31.90') W.C. an aluminum tag #951 in a R/R tie fence post bears N 45° 30' 40" W 34.37'(34.35')

#### MONUMENT DETAIL

below.

T5N R28E R29E 1/4 S25 | S30 1988 L.S 951

# OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

811632.66 8521731.97

## MONUMENT SET (PROCEDURES AND DESCRIPTION)

## NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 71° 57' 35" E 33.05' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 34° 31' 06" E 54.59'

# LOCATION AND COMMENTS

From the intersection of Walls road with Ott road, go North on Ott road 0.5 miles to corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH

REGISTERED PROFESSIONAL LAND SURVEYOR

levard

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L\_5

06-265-2