OREGON CORNER RESTORATION FORM SECTION: 19 TOWNSHIP: 5N RANGE: 29E N-1 COUNTY: UMATILLA **DATE**: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED NW Section 19 UNRECORDED SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1988 county contract in T5N R28E; Edwards set 1"x30 iron pipe with 2 3/8" brass cap. MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE Found 2 3/8" brass cap 4" above the surface stamped as detail. MONUMENT DETAIL T5N R28E R29E S13|S18 S24|S19 1988 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 819576.79 8521601.61 MONUMENT SET (PROCEDURES AND DESCRIPTION) NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 59° 05' 11" E 59.69' A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 66° 51' 07" W 45.61' A 5/8 x 30 Iron Rebar with plastic cap #951 bears S 47° 43' 31" W 34.05' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 12° 13' 06" E 52.00'

LOCATION AND COMMENTS

From intersection of Craig Rd. with Hwy # 730, go West on 730 one mile. Corner lies approximately 500' South of Hwy.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS

RENEWS 12/31/05

c:\Works\Restform\L-

06-265-C