OREGON CORNER RESTORATION FORM N-17 RANGE: 29E SECTION: 15 TOWNSHIP: 5N DATE: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY NOT FOUND CORNER DESIGNATION RENEWED UNRECORDED SE Section 15 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1983 Edwards set a 1"x30" iron pipe with a 2 3/8 brass cap. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE Found 2 3/8" brass cap at the surface of the ground stamped as below. MONUMENT DETAIL T5NR29E 15 | 14 22 | 23 1983 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 819878.48 8542804.89

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 78° 43' 06" E 24.49'
A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 66° 27' 55" W 26.08'
A 5/8 x 30 Iron Rebar with plastic cap #951 bears S 44° 09' 20" W 83.09'
A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 10° 02' 51" E 83.51'

LOCATION AND COMMENTS

From intersection of hwy 730 with Hat Rock Road go Northwesterly on Hat Rock Road 0.25 miles. Corner lies just South of North R/W fence.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\L-5