# OREGON CORNER RESTORATION FORM RANGE: 29E N-5 SECTION: 19 TOWNSHIP: 5N COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED UNRECORDED NE Section 19 SURVEYED IN REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1991 Edwards found mound of stone & set 2 1/2' Brass disk in concrete. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE Found 2 1/2" brass disk stamped as below in concrete W.C. a 5/8 "iron rebaar with aluminum tag #951 bears N 89° 49' 06" W 17.22' W.C. a 1/2" iron rebar with aluminum tag #951 bears N 0° 05' 19" W 12.83 (12.79')

## MONUMENT DETAIL

T5NR29E 18 | 17 19 | 20 1991 LS951

## OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

819644.42 8526918.50

### MONUMENT SET (PROCEDURES AND DESCRIPTION)

### NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 69° 00' 43" E 74.27' A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 0° 03' 16" W 52.65'

#### LOCATION AND COMMENTS

From intersection of Craig Rd & Hwy 730 go North 550' & West 50' to corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 16, 1971
G. DENNIS EDWARDS

9 5 1 RENEWS 12/31/05

c:\Works\Restform\L-5

06-265-C