

**OREGON CORNER RESTORATION FORM**

SECTION: 20 TOWNSHIP: 5N RANGE: 29E N-9

COUNTY: UMATILLA DATE: 12/05

**CORNER DESIGNATION**

NE Section 20

- CONDITION REPORT ONLY
- NOT FOUND
- RENEWED
- UNRECORDED
- SURVEYED IN
- REFERENCED OUT

**PREVIOUS RENEWALS/SURVEYS ETC.**

Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1991 Edwards set a 1"x30" iron pipe with a 2 3/8 brass cap.

**MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE**

Found 2 3/8 brass cap out of position. It bears N 85° 03' 31" E 3.56'. It was set in error. A 2" iron pipe 6" below surface bears S 89° 50' 34" W 68.68', origin unknown. A 3 3/4 brass cap U.S. BM bears N 18° 20' 18" E 19.25'(19.08')

**MONUMENT DETAIL**

T5NR29E  
17 | 16  
20 | 21  
2005  
951

**OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:**

819658.43  
8532234.26

**MONUMENT SET (PROCEDURES AND DESCRIPTION)**

By retracing Edwards 1991 survey for Conforth, I set a 1"x30" iron pipe with a 2 3/8" brass cap stamped as above flush with the surface.

**NEW ACCESSORIES FROM WHICH**

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 43° 39' 32" W 60.72'

**LOCATION AND COMMENTS**

From intersection of Salmon Point Drive with hwy 730 go west on hwy 730, 1.0 miles. Corner lies approximately 1700' North of Highway.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC  
PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH  
WITNESS: J. JOSEPH

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*G. Dennis Edwards*

OREGON  
JULY 16, 1971  
G. DENNIS EDWARDS  
9 5 1

RENEWS 12/31/05

06-265-C