OREGON CORNER RESTORATION FORM

SECTION 19, 24, 25, 30 TOWNSHIP 5 NORTH RANGE 29 EAST, RANGE 30 EAST

R-25

COUNTY: UMATILLA

DATE DEC/22

CORNER DESIGNATION

SECTION CORNER

X CONDITION REPORT ONLY

__NOT FOUND RENEWED

_UNCOVERED

SURVEYED IN

REFERENCED


PREVIOUS RENEWALS / SURVEYS, ETC.

SURVEYED IN 1861 BY PAYNE UNDER CONTRACT #100, HE SET A POST AND MADE MOUND. IN 1970 HARRIS SET 1" X 36" IRON PIPE WITH BRASS CAP.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

FOUND 2 1/2" BRASS CAP STAMPED AS BELOW.
FOUND 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED LS 951 BEARS N 79'20'15" E, 198.33'.
FOUND 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED LS 951 BEARS S 68'41'31" W, 999.31'.
FOUND 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED LS 951 BEARS S 12'04'52" W, 214.44'.
FOUND 5/8" IRON ROD WITH YELLOW PLASTIC CAP STAMPED LS 951 BEARS S 88'38'55" E, 235.64'.

MONUMENT DETAIL



8553439.29

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

LOCATION AND COMMENTS

FROM INTERSECTION OF COLD SPRINGS HIGHWAY AND WALLS ROAD
GO SOUTHWEST ALONG WALLS ROAD
+/- 1.35 MILES. CORNER FALLS
+/- 150 FEET NORTHWEST OF RÓAD

FIRM/AGENCY

PRIMM LAND SURVEYING, INC. P.O. BOX 1322 HERMISTON, OREGON 97838

LAND SURVEYOR BRIT L. PRIMM

WITNESS KEITH P. PRIMM SURVEYOR'S SEAL

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON JULY 13, 1999 BRIT L. PRIMM 48509

EXPIRATION DATE: 12/31/24