OREGON CORNER RESTORATION FORM SECTION:27 TOWNSHIP: 5N T-17 RANGE: 29E COUNTY: UMATILLA DATE: 12/05 CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED E1/4 Section 27 UNRECORDED X SURVEYED IN X REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Nothing found

MONUMENT DETAIL

T5NR29E W.C. 1/4 20.00' 27 | 26 2005 L.S 951

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

811962.87 8542943.10

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I computed the location. Corner falls inside a storage shed. Not set.

NEW ACCESSORIES FROM WHICH

A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 83° 05' 35" E 37.72'
A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 18° 51' 31" E 118.01'
A 1"x30" Iron Pipe with 2 3/8" brass cap stamped as above bears N 89° 49' 10" E 20.00'
A 1"x30" Iron Pipe with 2 3/8" brass cap stamped as above bears N 0° 05' 59" W 20.00'

LOCATION AND COMMENTS

From the intersection of Walls road with Marks road go North on Marks road 0.5 miles to a small storage shed.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH REGISTERED PROFESSIONAL LAND SURVEYOR

& Dennie Dwards

OREGON JULY 16, 1971 G. DENNIS EDWARDS 9 5 1

RENEWS 12/31/05

c:\Works\Restform\I_5

06-265-C