OREGON CORNER RESTORATION FORM SECTION:31 TOWNSHIP: 5N RANGE: 29E V-5 DATE: 12/05 COUNTY: UMATILLA CONDITION REPORT ONLY CORNER DESIGNATION NOT FOUND RENEWED NE Section 31 UNRECORDED SURVEYED IN X REFERENCED OUT PREVIOUS RENEWALS/SURVEYS ETC. Originally surveyed by Davenport under Contract # 101 in 1861. He set post and made mound. In 1910 Kimbrell set a 3/4" iron pipe. In 1984 Edwards set a 2" brass disk in concrete over iron pipe. MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE Found a 2" brass disk at the surface of a paved road stamped as below. W.C. an aluminum tag # 951 in a power pole bears S 73° 57' 14" E 71.18'(71.20') W.C. an aluminum tag # 951 in a power pole bears N 51° 11' 05" W 40.09'(40.03') W.C. an aluminum tag #951 in a R/R tie fence post bears S 49° 58' 41" E 33.58'(33.06') MONUMENT DETAIL T5NR29E 30 | 29 31 | 32 1989 L.S. 951 OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET: 809100.87 8527100.43 MONUMENT SET (PROCEDURES AND DESCRIPTION) NEW ACCESSORIES FROM WHICH A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 55° 51' 19" W 26.44' LOCATION AND COMMENTS At the intersection of Craig road & Walls road. SURVEYOR'S SEAL REGISTERED FIRM: EDWARDS SURVEYING LLC **PROFESSIONAL** PO BOX 763 - HERMISTON OR 97838 LAND SURVEYOR D. Dennis Elward PARTY CHIEF: R. SMITH WITNESS: J. JOSEPH OREGON G. DENNIS EDWARDS 951 RENEWS 12/31/05

:\Works\Restform\L-5

06-265-C