

OREGON CORNER RESTORATION FORM

SECTION:36 TOWNSHIP: 5N RANGE: 29E Z-21

COUNTY: UMATILLA DATE: 12/05

CORNER DESIGNATION

SW Section 36

- CONDITION REPORT ONLY
- NOT FOUND
- RENEWED
- UNRECORDED
- SURVEYED IN
- REFERENCED OUT

PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Maxon & Hurd under Contract # 50 in 1860. They set post and made mound.

MONUMENTS AND ACCESSORIES FOUND: CONDITON AND SOURCE

Nothing found.

MONUMENT DETAIL

SC
T5NR29E
35|36
2005
951

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

804110.84
8548362.99

MONUMENT SET (PROCEDURES AND DESCRIPTION)

By single proportion I set a 1"x30" iron pipe in concrete with a 2 3/8" brass cap 6" above the ground stamped as above.

NEW ACCESSORIES FROM WHICH

- A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 47° 27' 54" E 798.32'
- A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 37° 23' 12" E 786.89'
- A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 36° 27' 46" E 1597.08'
- A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 31° 58' 17" E 1513.88'

LOCATION AND COMMENTS

Corner lies 800' into the trees of Cold Springs Reservoir from the Southeast edge of trees.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC
PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH
WITNESS: J. JOSEPH

REGISTERED
PROFESSIONAL
LAND SURVEYOR

G. Dennis Edwards

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951

RENEWS 12/31/05