

OREGON CORNER RESTORATION FORM

SECTION: 36 TOWNSHIP: 5N RANGE: 29E Z-25

COUNTY: UMATILLA DATE: 12/05

CORNER DESIGNATION

SE Section 36

- CONDITION REPORT ONLY
- NOT FOUND
- RENEWED
- UNRECORDED
- SURVEYED IN
- REFERENCED OUT

PREVIOUS RENEWALS/SURVEYS ETC.

Originally surveyed by Maxon & Hurd under Contract # 50 in 1860. They set post and made mound. In 1953 US Fish and Wildlife set a 3" brass cap.

MONUMENTS AND ACCESSORIES FOUND: CONDITION AND SOURCE

Found 3" brass cap in concrete, stamped as below.

MONUMENT DETAIL

T5N
R29E R30E
SEC36 | SEC31
SEC 6
T4NR30E
1953

OREGON STATE PLANE COORDINATES, NORTH ZONE, NAD 83(91) INT. FEET:

804185.06
8553643.23

MONUMENT SET (PROCEDURES AND DESCRIPTION)

NEW ACCESSORIES FROM WHICH

- A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 0° 51' 38" E 31.30'
- A 5/8" x 30" Iron Rebar with plastic cap #951 bears N 89° 56' 25" W 34.46'
- A 5/8" x 30" Iron Rebar with plastic cap #951 bears S 0° 16' 34" W 42.92'
- A 3" brass cap in concrete (N.E. corner of T4N R29E) bears S 89° 57' 21" W 507.49'

LOCATION AND COMMENTS

0.1 miles East of the P.I. of a curve where the Highland Extension to Cold Springs road turns East. Corner lies 1' south of a fence corner.

SURVEYOR'S SEAL

FIRM: EDWARDS SURVEYING LLC
PO BOX 763 - HERMISTON OR 97838

PARTY CHIEF: R. SMITH
WITNESS: J. JOSEPH

REGISTERED
PROFESSIONAL
LAND SURVEYOR

G. Dennis Edwards

OREGON
JULY 16, 1971
G. DENNIS EDWARDS
951

RENEWS 12/31/05