OREGON CC NER RESTORATION FORM
Section 26, 25, 35, 36 Township 5N Range 30E
County Umatilla Date: 09-11-2006 Corner Designation: 5N30E V21
Previous Renewals / Surveys, etc. X Surveyed In Referenced Out
08–1861 S.Payne - Subdv (100) "Set-charred stake with mound trench and pits as per instrs for corner to secs 25, 26, 35, 36."
08-1934 ODOT J.A.Phelps (Dwg 58-1-1) Tie to found "Fc.Cor." of 5N30E T21 to found (V21) "2730.0' to Sec.Cor(Old Fc.Cor.)
10-1940 ODOT (Dwg 5B-29-11) "Fc.Cor." corner indicated on map
Monument and Accessories Found: (condition and source)
Searched for and did not find charred stake or fence post. Plowed field.
DIAGRAM
w ★ E W #
S1.26 'E 443.05ft
S26 S25
S35 S36
2006 PLS 852 N87 °35 'E S86 °30 'W
Buried 24" below 45.78ft surface of the ground.
5' steel t-post with a UCSM sign facing North
Set 2-3/8"dia. Brass cap 5/8"dia. x 30" long Iron on a 1-1/2" x 30" long • Rebar with a 1.3"dia. Galvanized pipe monument. Red plastic cap.
MONUMENT(S) AND ACCESSORIES SET (Procedures and Description) Set a 2-3/8"dia.Brass Capped monument (stamped as shown) on
Set a 2–3/8"dia.Brass Capped monument (stamped as shown) on a 1–1/4"ID x 30"long galvanized pipe 24" below the ground surface. Set a Umatilla County Survey Marker sign 6" North of the Northern RM facing North toward the access road. REFERENCES SET:
Set four $(5/8"$ dia x $30"$ long Iron rebar with a 1.3" dia. Red plastic cap) to the bearings and distances from monument shown above in the sketch.
Made GPS tie to TRI Stations LAURILA RESET RB 1379 and WALLS RB 1396 Latitude 45 °52'41.57740"N Longitude 119°00'56.73743"W NAD 83(1991) Oregon State Plane Coord North Zone 809766.99 Easting 8580105.95 Ortho Height 1000.54 Ellipsoidal Height 931.34
Location and Comments Compass Declination Surveyors Seal 18°E
Beginning 1.5 miles West of HWY 37 and the S. Fork Cold Spring Road. South on Umatilla County Road 1172 (KOSMOS RD) 0.59 miles to a East field access gate. Thence East 0.83 miles to the 1/16th corner. Thence East approx 980 feet through the field gate to the buried corner in the plowed field. REGISTERED PROFESSIONAL LAND SURVEYOR
RECEIVED BY: Firm / Agency Danidh. Haddock
Date 02-07 OHC Haddock Surveying P. O. Box 1574 Pendleton, OR 97801 (541) 276-2174 Page 1940 OREGON JULY 12, 1968 DAVID L. HADDOCK 852 RENEWS 6-30-07