
History of original corner establishment: None



No record of subsequent remonumentation found in County Records .

None

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 6 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence posts South and West on line from corner and attached signs 54-2 and 54-9.

Established 2 new BT's: A 10½" bull pine bears N28½ E 223.5ft.scribed NE 1/16 S 30 BT.

A 13½" bull pine bears N 48½°E 228.3 ft. scribed NE 1/16 S 30 BT.

BT's have 54-3 and 54-4 signs attached and a 6" red band painted around them above blaze. Location marker on fence post where fence crosses road. Corner 1500' feet + West of location poster.

Used steel tape and magnetic comoass with See map of survey This corner set August 21, 1979	REGISTERED PROFESSIONAL LAND SURVEYOR	T5 5 R3IE
Witnesses: Greg Flowers L.S.I.T. Brent Reynolds	Willia R. Wells	NE 16 530
	OREGON JULY 22, 1977 WILLIAM R. WELLS 1106	1979 PLS 1106
Office of County Surveyor State of Oregon , I hereby cert	County of Umatilla	office
for record on the day of		
(COUNTY OFFICIAL)	by	

RECEIVED BY

Umatilla County Surveyor

Bate <u>Dept 4. 1979</u>
Sec'd By M. Nughes

Form R6-7100-57 (9/71)

GPO 796-333