USDA-FOREST SERVICE	
Index File No. T-2	CORNER RECORD (SEARCH) Tract or Survey No. Sec. 30 Cor. No. C.W. 1/16
T	R.D. Ukiah (Ref. FSM 7151.4) Survey No. Sec. 30 No. C.W. 1/16
Merid. Willamette	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
	None
GEC 30	
N CW/16	
T5S R31E W.M.	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND None
PHOTO IDENTIFICATION DATA	
Photo No	
Filed At.	
Object ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER Corner located in the bottom of a small canyon on the east side of a
PLANE COORDINATE POSITION DATA	dry stream bed.
State Zone X Y	
Estab. By Agency 8	
Signature Willia Rulella	Title Division Headquarters Date 7100-52-(3/68) 5

CORNER RECORD (PERPETUATION)

NONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Set 2" x 30" galvanized iron pipe with a brass cap \$5 inches in ground with a mound of stone to the cap, marked: T55 R31

Set steel fence post on line North of corner and attached signs 54-2 and 54-9.

T55 R31E C W/16 C 930 1979 PL51106

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Set 2 New BT's:

BT's have a lower blaze scribed BT with a brass washer stamped PLS 1106 nailed flush.

Attached signs 54-3 and 54-4 and painted red ring around BT's.

Work Done By William R. Wells Title PLS 8/21/79 State Registration No. 1106

Certified Cor. Record Prepared ? Yes X No Filed At: Umatilla County Surveyor's Office Date 11

Note: This corner was established in error in 7/79 and bearing trees established. When the corner was established in its true position, scribing and signs were removed from the BT's referencing the erroneous position. From the correct corner position:

A $8\frac{1}{2}$ " red fir bears N $16\frac{1}{2}$ °E 50.5 ft with open blaze A 8" bullpine bears S $35\frac{1}{2}$ °E 42.3 ft with open blaze

Index File No. T. R. M. Tract or Surv. No. Sec. 30 Cor.C. W. 1/58
T-2 5S 31E Williamette