File No	CORNER RECORD (SEARCH) Tract or Sec 30 Cor. C \(\frac{1}{4}\) R.D. Ukiah (Ref. FSM 7151.4) Umatilla N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND None
SEC 30	
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
	6
Photo No Filed At Object Ident dent. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER Corner located in the bottom of small canyon on east side of days
Photo No. Filed At. Object Ident. dent. By Signature PLANE COORDINATE POSITION DATA	7 canyon on east side of dry
Photo No. Filed At. Object Ident. dent. By Signature PLANE COORDINATE POSITION DATA	7 canyon on east side of dry
LANE COORDINATE POSITION DATA	stream bed.

CORNER RECORD (PERPETUATION)

Set a 2" x 30" galvanized iron pipe, with brass cap 24 inches in ground with a mound of stone to the cap marked:

Set steel fence post on property line North of corner and attached

signs 54-2 and 54-4.

1979 PLS 1104

T55 R31E

C4530

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 8" red fir bears S 65°E 9.7 ft. to center $C_{\frac{1}{4}}$ S30 B/s.

A 10" red fir bears S8°E 17.1 ft. to center scribed C½ S 30 BT. BT's have a lower blaze scribed BT with a brass washed stamped PLS 1106 nailed flush.

Attached signs 54-3 and 54-4 and red ring around BT's.

Pointed a

MONUMENT SET, OR WORK DONE TO PRESER

Work Done By William R. Wells Title PLS Date No. State Registration No. or Agency 1106 Filed At: Umatilla County Surveyors Office Certified Cor. Record Prepared ? Yes X No REMARKS NOTE: This corner was erreously established in 7/79 and bearing trees established when the corner was established in its true position, scribing and signs were removed from BT's referencing the

erroneous position. From the correct corner position; A 13" red fir bears N 68½°E 177½ w/open blazes.

A $11\frac{1}{2}$ " red fir bears N85°E 156' \pm w/ open blazes.

Tract or Surv. No. Index FriegNo. 55T. 31ER. Willamette