Index No. T-4 History of original corner establishments DIAGRAM None CEYL SEC 30 T55 R31E W.M No record of subsequent remonumentation found in County Records . Description of corner evidence found: None Description of monument and accessories I established to perpetuate the original location of this corner At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 20 inches in the ground and surrounded with a mound of stones to the cap. Set steel fence post North and West of corner and attached signs 54-2 and 54-9. Established 2 new BT's: A 13" bull pine bears S75°E 114.5 ft. scribed CE 1/16 S 30 BT. A 13½" bull pine bears \$52½°E 91.3 ft. scribed CE 1/16 \$ 30 BT. BT's have a lower blaze scribed BT with a brass washer stamped PLS 1106 nailed to it. BT's have 54-3 and 54-4 signs attached and a 6" red band painted around them above blaze. Location poster on West side of road 300'+east of corner. Used steel tape and magnetic compass with  $19\frac{1}{2}^{\circ}$  east declination. Measured to center of Bts. See map of survey REGISTERED 55 RBIE PROFESSIONAL August 20, 1979 This corner set LAND SURVEYOR Witnesses: Greg Flowers L.S.I.T. 5 30 **Brent Reynolds** OREGON 1979 JULY 22, 1977 PLS 1106 WILLIAM R. WELLS 1106 County Surveyor Umatilla County of ... Oregon I hereby certify that the within instrument was filed in this office (COUNTY OFFICIAL) RECEIVED BY

Umatilla County Surveyor

Form R6-7100-57 (9/71)

GPO 796-333