Territorial Control of the Control o	CORNER RECORD (SEARCH) Tract or Sec 30 Cor. S W 1/16  R.D. Ukiah County Umatilla  N.F. Umatilla  State Oregon
ORNER DIAGRAM	N.F. Umatilia State Oregon  DESCRIBE CORNER MONUMENT FOUND
	Noné
T	
9EC 30	
526 30	
SWYIG	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
<u></u>	None None
T5S R31E W.M.	
4	
HOTO IDENTIFICATION DATA	<del>'</del>
hoto No	
iled At	
bject Ident	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
dent. By	Located on flat on top of Rocky Ridge in stand of small bull pine.
LANE COORDINATE POSITION DATA	i stand or small borr pine.
tate Zone	
stab. By	
Agency 8	
William R. wells	

٠,

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT Set a 2" x 30 " galvanized iron pipe with a brass cap 9 inches T55 R31E

in ground with a mound of stones to the cap marked:

Set steel fence post on property line North and West of corner and attached signs 54-2 and 54-9.

SW/16530 1979 PLS 1106

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EX

Set 2 New BT's:

BT's have a lower blaze scribed BT with a brass washer stamped PLS 1106 nailed flush.

Attached signs 54-3 and 54-4 and painted red ring around BT's,

State Registration No. 1106 Work Done By William R. Wells Title PLS Filed At Umatilla County Surveyor's Office Certified Cor. Record Prepared ? Yes X No Date REMARKS

This corner was established in error in 7/79 and bearing trees established. When the corner was established in its true position, scribing and signs were removed from 1 BT referencing the erroneous position. From the true corner position: A 9" Bullpine bears N 1° E 18.8 feet with open blaze.

Τ. Tract or Surv. No. Index File No. R. M. Willamette U-2 **5**S 31E