
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None



No record of subsequent remonumentation found in County Records .

None

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 22 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence post North and East of corner on property line and attached signs 54–2 and 54–9. Established 2 new BT's: A  $8\frac{1}{2}$ " red fir bears N87°E 70.8 ft. scribed CS 1/16 S 30 BT.

A 8½" red fir bears N81° E 69.1 ft. scribed CS 1/16 S 30 BT.

BT's have a lower blaze scribed BT with a brass washer stamped PLS 1106 nailed to it. BT's have 54-3 and 54-4 signs attached and a 6" red band painted around them above blaze.

See map of survey  This corner set August 20, 1979	REGISTERED PROFESSIONAL LAND SURVEYOR  REGISTERED C	\
Witnesses: Greg Flowers L.S.I.T. Brent Reynolds	Willia R. Wells  OREGON JULY 22, 1977 WILLIAM R. WELLS  1106  S/16 530	)
Office of County Surveyor  State of Oregon , I hereby certify	County of Umatilla that the within instrument was filed in this office	
for record on the day of	by(DEPUTY)	

RECEIVED BY

Umatilla County Surveyor

Rec'd By M. Mughes
No. Q-1164-B

Form R6-7100-57 (9/71)

# GPO 796-333