
History of original corner establishment:

None



No record of subsequent remonumentation found in County Records .

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 22 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence posts on property line South and East of corner and attached signs 54–2 and 54–9. Established 2 new BT's:

A 11" bullpine bears N30°W 2.5 ft. scribed W 1/16 S 30 BT.

A 10" bullpine bears \$57°W 55.3 ft. scribed W 1/16 \$31 BT.

BT's have lower blaze scribed BT with a brass washer stamped PLS 1106 nailed to it.

BT's have 54-3 and 54-4 signs attached and a 6" red band painted around them above blaze.

See map of	ape and magnetic compass with survey set July 29, 1979	REGISTERED PROFESSIONAL LAND SURVEYOR	TSS K31E
Witnesses:	Witnesses: Greg Flowers, L.S.I.T. Brent Reynolds	Willia R. Wells	W/14 530
		OREGON JULY 22, 1977 WILLIAM R. WELLS 1106	1979 PLS1106
Office	of County Surveyor	County of Umatilla	
State o	of , I hereby certify	that the within instrument was filed in this	office
for rec	ord on the day of		
	(COUNTY OFFICIAL)	(DEPUTY)	mining of the second

RECEIVED BY

Date Sept 4, 1979
Ricc'd By M. Mughou
No. Q-1164-8

Form R6-7100-57 (9/71)

∴ GPO 796 333