


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

B-18

History of original corner establishment:

No record of previous monumentation.



Description of corner evidence found:

None.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2½"x30" alum. pipe with a 3" alum. cap containing a magnet, marked:

NW 1/16 S2
PLS 1832
1984

From the corner:

A Lodgepole, 11" dia., N20¼°E, 114.6 ft. marked: NW 1/16 S2 BT
A Lodgepole, 9" dia., N4°W, 117.2 ft. marked: NW 1/16 S2 BT

BTs have blaze and a 6" stripe painted red, a BT tag, a "Land Survey Monument" sign and an alum. "PLS 1832" washer nailed to the bottom of the blaze. There is a 6' steel fence post with a "Land Survey Monument" sign within 5' of the corner.

Measured to center of BTs using steel tape and staff compass. Magnetic declination set at 20°E.

September 15, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Fayette S. Munro

OREGON
JULY 13, 1979
FAYETTE S. MUNRO
1832

Office of Surveyor County of Umatilla
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 10 day of October, 1984
David H. Klumbein by [Signature]
(COUNTY OFFICIAL) (DEPUTY)