USDA-FOREST SERVICE		
Index File No. <u>B-22</u>	CORNER RECORD (SEARCH) Tract or Survey No	Cor. NW $\frac{1}{16}$
T <u>5S</u> R. <u>33E</u>	_ R.DUkiah County Umatilla	No16
Merid. <u>Willamette</u>	N.F. Umatilla State Oregon	
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	
$ \begin{array}{c c} NW & \frac{1}{16} & S1 \\ \hline \end{array} $	None Set	
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND None Set	2
PHOTO IDENTIFICATION DATA	i Home Set	
Photo No		
Object IdentIdent. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO H	OW TO REACH CORNER
PLANE COORDINATE POSITION DATA State Zone Y Estab. By	Corner falls 16 ft north & 3 ft east of E-S fen Take USFS Road No. 1455 south off of State Hwy tag on west side of road. Follow fence west ap to corner.	nce corner.
Agency 8		
Trous soldier	Title Division Headquarters Date QRLS 1294 9577	7100-52 (3/68)

CORNER RECORD (PERPETUATION)

CORNER RECORD (PERPETUATION)		
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT At surveyed point set 2 1/2"X30" galvanized pipe with brass cap stamped:	T5S R33E NW 16 S1	
Set pipe 20" in ground with mound of stone to cap.	1980 OR PLS 1294	. 9
ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRIBE Bearing Trees: A Lodge Pole Pine 6" dia bears N32 OW, 65.2 ft., scribed NW1/16 SA Ponderosa Pine 11" dia bears S42 E, 32.5 ft., scribed NW1/16 SA Attached 54-3 & 54-4 signs to both BTs. Attached brass washer	S1 BT. S1 BT. stamped	
LS 1294 to foot blaze of both BTs. Painted blazes and 6" band both BTs Red. Attached 54-2 & 54-4 signs to metal post 5 ft ea Attached 54-2 & 54-9 signs to metal post 5 ft south of corner.	st of corner.	10
Work Done By. R. C. Orton Title Party Chief Dote 6-19-80 State Reg	istration No.	
Certified Cor. Record Prepared ? (Yes) No Filed At:	Date	
Witnesses: R. Orton G. Orton D. Allen		

Index File No. T. R. M. Tract or Surv. No. Cor. 13
B-22 55 33E