CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM

T5S R33E

CW 1/16 S2

No record of previous monumentation.

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½"x30" alum. pipe with a 3" alum. cap containing a magnet and marked:

W 1/16 PLS 1832 1984

From the corner: A Lodgepole, 10" dia., S3 $^{\rm O}$ W, 42.0 ft. marked: CW 1/16 S2 BT A Lodgepole, 7" dia., S72 $^{\rm O}$ W, 59.6 ft. marked: CW 1/16 S2 BT

BTs have blaze and a 6" stripe painted red, a BT tag, a 'Land Survey Monument' sign and an alum. "PLS 1832" washer nailed to the bottom of the blaze. There is a 6' steel fence post with a 'Land Survey Monument" sign within 5' of the corner.

Measured to center of BTs using steel tape and staff compass. Magnetic declination set at 1640E.

September 15, 1984.

REGISTERED PROFESSIONAL

FAYETTE S. MUNRO

Durveyor County of Umatilla State of OREGO ... I hereby certify that the within instrument was filed in this office for record on the ... O day of October ... 1984.

DOUGHER DOUGHER ... (COUNTY OFFICIAL)

ODEPUTY)

Form R6-7100-57 (9/71)

GPO-798-276

84-132-R