
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No corner was originally set.



Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point set 2 1/2"X30" galvanized pipe with brass cap stamped:

Set pipe 24" in ground with mound of stone to cap.

T5S R33E 1980 OR PLS 1294

A Lodge Pole Pine 14" dia bears S74^oE, 73.0 ft., scribed CW1/16 S1 BT. A Lodge Pole Pine 5" dia bears S1 W., 73.6 ft., scribed CW1/16 S1 BT.

Attached 54-3 & 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs Red. Attached 54-2 & 54-4 signs to metal post 5 ft north of corner. Attached 54-2 & 54-9 signs to metal post 5 ft west of corner.



I hereby certify the above corner monument was established as herein described on June 19, 1980.

Witnesses: R. Orton

G. Orton

D. Allen

Office of	County Surveyor	County of Umatilla
State of	Oregon , I hereby certify	that the within instrument was filed in this office 19,80 by Sitty Shatto
Dan	id Drumber	by Billy Shall
	(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO--798-276

R-187-B