Index File No. C-25 T	CORNER RECORD (SEARCH) Tract or Cor.  R.D. Ukiah County Umatilia  N.F. Umatilla State Oregon	—-
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND	=
R33E R33 $\frac{1}{4}$ R33 $\frac{1}{2}$ E	A diligent search was made and no evidence of original stone or its accessories could be found.	
31   33	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND	2
<b>'</b> .	A diligent search was made and no evidence of original stone or its accessories could be found.	
HOTO IDENTIFICATION DATA	<u>5</u>	
hoto No		
iled At.		
blject ident dent. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNE  Corner falls on flat ground approximately 50 feet south of  Camas Creek and 150 feet south of	3 R
LANE COORDINATE POSITION DATA	Camas Creek and 150 feet south of State Hwy. 244.	
tate Zone		
stob. By		
Signature Signature	Title Division Headquarters Date 7100 70 100	_4
2700000	Division   Headquarters   Date   7100-52 (3/68)	i)

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT T5\$ At point established by single proportion measurement between N.E. R33 1 E Corner and S.E. Corner of S1, T5S, R33E. Set 25"x30" galvanized pipe with brass cap stamped: **R33E** Set pipe 24" in ground with mound of stone to cap. OR PLS 1294

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A P. Pine 17" dia. bears SØOOW, 25.2 ft., scribed 1/4 S1 BT. A Lodge Pole Pine 5" dia. bears N420W, 69.2 ft., scribed 1/4 S1 BT. Attached 54-3 and 54-4 signs to both BTs. Attached brass washer stamped L.S. 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs red. Attached 54-2 and 54-4 signs to metal post 5 ft. south of corner. Attached 54-2 sign to metal post 5 ft. west of corner.

				10
Work Done By, R.C. Orton	Title_	Party Chief	Date 6/13/80 State Registration No.	
Certified Cor. Record Prepared ? Yes		filed At:	Date	11
		REMARKS		

Witnesses: R. Orton G. Orton D. Allen

Cor. Tract or Surv. No. R. Index File No. T. ·U.S. G.P.O. 1977-725-576/586 33E C-25

USDA-FOREST SERVICE	
Index File No. C-25	CORNER RECORD (SEARCH) Tract or Cor.  (Ref. FSM 7151,4) Survey No. No.
T <u>5 S</u> R. <u>33 E</u>	R.D. <u>Ukiah</u> <u>County</u> Umatilla
Merid. Will.	N.F. Umatilla State Oregon
CORNER DIAGRAM	DESCRIBE CORNER MONUMENT FOUND
Sec.	None
1 1 -	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND
PHOTO IDENTIFICATION DATA	None. North-south blaze line. Apparant corner location is on Camas Creek flood plain. Many down and very rotten trees in this area. General topography does not fit the original calls very well.
	Carrs very werr.
Photo No Filed At.	<b>-  </b>
Object Ident	OCCUPIES CORNER LOCATION RELATIVE TO MEAN BY SECTION RELATIVE
Ident. By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature	7
PLANE COORDINATE POSITION DATA	
State Zone	_
×	
Υ	
Estab. By	
Signature B. Moore	Title Division Headquarters Date 7100-52 (3/68)
	2 / ( 5

## CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

		10
Work Done By Title	State Registration No.	
Certified Cor. Record Prepared ? Yes No Filed At:	Date	

REMARKS

\_\_\_\_

Index File No. T.

R.

M.

Tract or Surv. No.

Cor.

13