USDA-FOREST SERVICE	** **			
Index File NoJ-24 T5S R33E	CORNER RECORD	(SEARCH) Tract o		Cor. E 1 No. E 16
1117	_R.D. <u>Ukiah</u>	. County <u>Umatilla</u>		
	N.F. Umatilla	State Oregon		
CORNER DIAGRAM	DESCRIBE CORNER MONUME	NT FOUND		
$E \frac{1}{16} \qquad \frac{$12}{$13}$	None Set			
Ņ				
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND			
•	None Set			
PHOTO IDENTIFICATION DATA	6			
Photo No	· [
Object Ident				
Ident. By	DESCRIBE CORNER LOCATION F	RELATIVE TO NEAR-BY FEA	TURES, ALSO HOW	TO REACH CORNER
Signature	T .			
PLANE COORDINATE POSITION DATA	Corner falls approx	\sim 80 ft. west of N	I-S Fence.	•
State Zone	·	,		
× ———	1			
Tatah Bu	I			
Estab. By				
Hound Sand	Title Division	Headquarters 1294	9r77	7100-52-(3/68)
				<u></u>

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT T5S R33E At surveyed point set 2 1/2"X30" galvanized pipe with brass cap stamped: 1980 Set pipe 24" in ground with mound of stone to cap. OR PLS 1294 ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE Bearing Trees: A Douglas Fir 8" dia bears N42°E, 12.5 ft., scribed E1/16 S12 BT. A White Fir 9" dia bears S830 W, 19.5 ft., scribed E1/16 S13 BT. Attached 54-3 & 54-4 signs to both BTs. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs Red. Attached 54-2, 54-4 & 54-9 signs to metal post 5 ft north of corner. Work Done By R. C. Orton Title Party Chief Dote 7-8-80 or Agency Title No. Date Certified Cor. Record Prepared ? (Yes) Filed At: REMARKS

L. Huntsman D. Allen

Witnesses:

R. Orton

Tract or Surv. No. Cor. M. Index File No. R. .0. 1977-725-576/58

33E