CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: No corner was originally set.

Index	File	No.	B-17			
DIAGRAM						
T55	R33	1/2	Ε			
N 1/16 S3 S2						

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner: At surveyed point set 2 1/2"X30" galvanized pipe with brass cap stamped:

Set pipe 10" in ground to rock with mound of stone to cap.

Bearing Trees:

A Ponderosa Pine 7" dia. bears S7°W, 100.2 ft., scribed N1/16 S3 BT. A Ponderosa Pine 7" dia. bears N72°E, 72.7 ft., scribed N1/16 S2 BT.

Attached 54-3 & 54-4 signs to both BT's. Attached brass washer stamped LS 1294 to foot blaze of both BTs. Painted blazes and 6" band around both BT's Red. Attached 54-2, 54-4 & 54-9 signs to metal post 6 ft west of corner.



I hereby certify the above corner monument was established as herein described on July 9, 1980.

Witnesses: R. Orton L. Huntsman D. Allen

Office of	.County .Surveyor	County of	Umatilla	
State of	Oregon , / hereb	y certify that the within	instrument was file	d in this office
for record	on the day of All	cember 198	0.	
Fla	nes Drumb	an by Bett	1 Shal	***************************************
*	(COUNTY OFFICIAL)		(DEPUTY)	

Form R6-7100-57 (9/71)

☆ GPO-798-276

R-187-B