## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

No corner was originally set

	_			
S2				
		2	•.,	

Description of corner evidence found:

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2"x30" galvanized pipe with brass cup stamped:


Set pipe 22" in ground with mound of stone of cap.

T5S R33 1/2E NW 1/16 S2 1980 OR PLS 1294

Bearing Trees:

A Lodge Pole Pine 7" dia. bears S62°W, 47.8 ft., scribed NW1/16 S2 BT. A Lodge Pole Pine 7" dia. bears N33°W 52.6 ft., scribed NW 1/16 S2 BT.

Attached 54-3 & 54-4 signs to both BTs. Attached brass washer stamped LS1294 to foot blaze of both BTs. Painted blazes and 6" band around both BTs Red. Attached 54-2 & 54-4 signs to metal post 5' south of corner. Attached 54-2 & 54-9 signs to metal post 5' west of corner.



I hereby certify the above corner monument was established as herein described on June 27, 1980.

Witnesses: R. Orton

G. Orgon

D. Allen

Office of County Surveyor	county of Umatilla
State of Oregon I herefy certify that	the within instrument was filed in this office
Land Dunley by	19.80
David Milmbun by	B. Shall
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO-798-276

R-187-B