USDA-FOREST SERVICE Index File No. D-18	CORNER RECORD (SEARCH) Tract or Cor. SW 1/16
T <u>5S</u> R. <u>33 1/2E</u> Merid. Willamette	R.D. Ukiah County Survey No No No
CORNER DIAGRAM	N.F. Umatilla State Oregon
$\begin{array}{c c} SW & \frac{1}{16} \\ \hline \end{array}$	There was no corner originally set.
	DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND None set.
PHOTO IDENTIFICATION DATA Photo No	
Object Ident dent, By	DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
Signature 7 PLANE COORDINATE POSITION DATA State Zone	Corner falls 10' East and 6' South of N-S-W fence corner. Also, 50' North of cattle guard in Road No. 5160-290
(
Signatules 8	Title Division Headquarters Date 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

	CORNER RECORD (PERPETUATION)		
	MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT TOS 33 1/2E		
	Attsurveyed point set 2 1/2" X 30" galvanized pipe with brassSW16,\$2		
	cap stamped:		
	set pipe 22" in ground with mound of stone to cap. 1980 OR PLS 1294	9_	
	ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE		
	A Tamarack 7" dia bears N88°E. 19.7 ft., scribed SW 1/10 SZ BI.		
٠.	A Douglas Fir 10" dia. bears N710W., 30.0 Ft., scribed SW 1/16 S2 BT.		
	Attached 54-3 & 54-4 signs to both BTs. Attached brass washer stamped LS1294 to New BTs. Painted blazes and 6" band around both BTs red. Attached 54-2 & 54-4 signs to metal post 6' west of corner. Attached 54-2 & 54-9 signs to metal fence post 6' north of corner.	10	
	Quan Projeton la No		
	Work Done by		
	Certified Cor. Record Prepared ? Yes No Filed At: Date		
	REMARKS		
	Witnesses: R. Orton		
	Witnesses: R. Orton G. Orton		
	D. Allen		
•	D. MIEII		

Index File No. T. R. M. Tract or Surv. No. Cor. 13

D-/8 55 33/1/2