## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established under G.L.O. Contract No. 457, in 1882 by Rufus S. Moore. Surveyor General's records state: Set post 4 ft long 4" square 24" in ground for Corner to Secs. 3 & 10 marked T5S R33 1/2E on E, S3 on N. and S10 on S. faces with 5 notches on S. and 1 notch on N. faces and mound of stone around post, from which:

| DIAGRAM | T5S | S3 | R33E | S12 | S10 | S10

A Pine 5 ins. diam. bears N43°E, 69 lks dist marked T5S R33 1/2E S3 BT.

## Description of corner evidence found:

No evidence of original post or mound of stones.

Found down and dead Pine 11" in dia. with visible scribing "R33", the rest of scribing had been destroyed towards base of tree, the higher scribing is grown over.

This corner was set by a Junior Survey and therefore, according to the BLM Manual Section 5-35 (3), is to be treated as a closing corner. The true corner position lies East 41.72 ft. of original corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

At a point record bearing and dist. from found BT set 2 1/2" X 30" galvanized pipe with brass cap stamped:

R33E | S3 R33E | S3 S12 | S10 1980 OR PLS 1294

set pipe 24" in ground with mound of stone to cap.

New Bearing Trees: A Tamarack 11" dia. bears N74 $^{\rm O}$ E, 69.7 ft. scribed T5S R33 1/2E S3 BT. A Lodge Pole Pine 7" dia. bears S51 $^{\rm O}$ E, 69.2 ft. scribed T5S R33 1/2E S10 BT.

Attached 54-3 & 54-4 signs to all BTs. Attached brass washer stamped LS1294 to new BTs. Painted blazes and 6" band around all BTs red. Attached 54-2 & 54-4 signs to metal fence post 5 ft south of corner. The 54-3 signs have  $\underline{\sf AM}$  marked on them.

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON
SEPTEMBER 23, 1927
HOWARD L. PERRY
1 2 9 4

I hereby cerfity the above corner monument was re-established as herein described on July 3, 1980.

Witnesses: R. Orton

R. Orton
D. Allen
L. Huntsman

Office of County Surveyor County of Umatilla
State of Oregon , I hereby certify that the within instrument was filed in this office for record on the day of County of State by State
(COUNTY OFFICIAL) (CEPUTY)

Form R6-7100-57 (9/71)

☆ GPO-798-276

R-187-B

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. E-13

History of original corner establishment: Corner established under G.L.O. Contract No. 457, in 1882 by Rufus S. Moore. Surveyor General's records state: Set post 4 ft. long 4" square 24" in ground for corner to Secs. 3 & 10 marked T5S R33 1/2E on E, S3 on N. and S10 on S. faces with 5 notches on S. and 1 notch on N. faces and mound of stone around post, from which:

DIAGRAM TRUE T5S R33E S3 R33½E S12 S10

A Pine 5 ins. diam. bears N43 $^{\rm O}$ E, 69 lks. dist. marked T5S R33 1/2E S3 BT.

The original corner was set by a Junior Survey and, therefore, according to BLM Manual Section 5-35(3) is to be treated as a closing corner. The original corner is 41.72 ft. west of the true corner position.

## Description of corner evidence found:

No evidence of original post or mound of stones.

Found down and dead Pine 11" in dia. with visible scribing "R33", the rest of scribing had been destroyed towards base of tree, the higher scribing is grown over.

Description of monument and accessories I established to perpetuate the

original location of this corner At surveyed True Corner position set  $2\frac{1}{2}$ "x30" galvanized pipe with brass cap stamped:

R33E S3 R33 1/2 S10 1980 OR PLS 1294

T5S

Set pipe 24" in ground with mound of stone to cap.

New Bearing Trees:

A Tamarack 11" dia. bears  $N51^{0}E$ , 31.1 ft., scribed T5S R33 1/2E S3 BT. A Lodge Pole Pine 7" dia. bears  $14^{0}E$ , 46.0 ft., scribed T5S R33 1/2E S10 BT.

Attached 54-3 and 54-4 signs to all BTs. Attached brass washer stamped LS 1294 to new BTs. Painted blazes and 6" band around all BTs red. Attached 54-2 and 54-4 signs to metal fence post 5 ft. south of corner. The 54-3 signs have  $\overline{\text{TRUE}}$  marked on them.

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON
SEPTEMBER 23, 1977
HOWARD L. PERRY
1 2 9 4

I hereby certify the above corner monument was reestablished as herein described on August 28, 1980.

Witnesses: R. Orton

D. Allen

L. Huntsman

Office of	County Surveyor	County of	Umatilla
	Oregon , I hereby certify that the within instrument was filed in this office the mind of Mcernier 1980 the found by A Market COUNTY OFFICIAL		
for record or	the pudgy of Sece	mber 1	980, ~
Han	of Trumber	by #	The to
	(COUNTY OFFICIAL)		(DEPUTY)

Form R6-7100-57 (9/71)

:: GPO 796-333

R-187-B